



Mercury
Breakthrough Indicator
For Carbon Absorbers
Hg BTI 2
(PN: 412)

Manual



1. Application

The Mercury BTI 2 (PN: 412) is qualitative (yes/no) colorimetric indicator for the end-of-service life of carbon absorbers and filters. It is designed to provide real-time indication of the breakthrough of mercury and mercury II compounds.

2. Specifications

a. Weight:	129.5g (4.6oz)
b. Dimensions:	11.43cm (4.5in), diameter 5.08cm (2.0in)
c. Inlet dimensions:	1.5" MNPT
d. Operating temperature:	-20°C to 55°C (-4°F to 131°F)
e. Operating humidity:	5% RH to 90%RH
f. Minimum detectable limit:	0.5mg/m ³ -hr at 30 cm/sec face velocity
g. Color change:	Off white to peach
h. Storage temperature:	4°C to 25°C, (39°F to 77°F)
i. Shelf life:	12 months at 4°C to 25°C, (39°F to 77°F)
j. Service life:	12 months
k. Light effect:	None

Cross interferences: Strong oxidizers. No other interferences or limitations are known.

3. Operating Instructions

- Ensure that packaging pouch is intact.
- Open packaging pouch by tearing off the top part from one of side notches.
- Remove the Breakthrough Indicator from the packaging pouch.
- Remove the 1.5" threaded plug from the carbon absorber outlet lid.
- Remove the protective red plug to activate the breakthrough indicator.
- Thread the Breakthrough Indicator into the 1.5" threaded carbon absorber outlet lid.



Caution: Only hand tighten indicator into carbon absorber

- Replace carbon absorber when the Breakthrough Indicator changes color to peach.



Unexposed



Exposed
Change carbon absorber

CHEMTEQ[®]

Chemteq, Inc., 600 West 24th Street, Suite B, Norfolk, Virginia 23517, Tel 757-622-2223, sales@chemteq.net
©2009 Chemteq, Inc.

www.chemteq.net

MP-4128100-092521-A